

# **Huntridge Theater**

**Las Vegas, Nevada**



Site Visit conducted by

Staff of the

*Nevada State Historic Preservation Office*

*October 11, 2016*



File Photo 1 (early 1990s)



File Photo 2 (early 1990s)



Installation of the new roof (1997)



Installation of new security fencing; restoration of marquee (late 1990s)

Photos from 2013 visit and 2016 visit

# Front Entrance & Marquee

*CCA funded projects include (per file):*

Restoration of Marquee





2013



2016



2013



2016






2013



2016



2013



2016



2013



2016





2013



2016

Photos from 2013 visit and 2016 visit

# Sidewalk, Paving & Fencing

*CCA funded projects include (per file):*

- Front block work
- Installation of concrete pad & exterior walkways
  - Resurfacing of parking lot
- Installation of security fencing





2013



2016



2013



2016

2013




2016







2013



2016





2013




2016



2013

2016



Photos from 2013 visit and 2016 visit

# Adjacent Building, rear & side façade

*CCA funded projects include (per file):*

- Installation of security fencing
- Removal of old & installation of new air conditioning units
- Removal of old roof & installation of new roof
  - Installation of fly loft



2013



2016





2013

2016







2013

2016





2013

2016





2013



2016





2013



2016



2013

2016







2013



2016

Photos from 2013 visit and 2016 visit

# General Maintenance

*CCA funded projects include (per file):*

- Updated electrical*
- Installed/updated sprinkler & fire alarm system*
- Rekeyed all locks*



2013

2016





2013


2016







2013



2016



2013



2016






2013



2016



2013

2016







2013

2016



Photos October 11, 2016 visit

## Interior Views



Lobby from Front Entrance



Visible in photo are broken tiles on lobby floor and stairs



Ceiling Of Lobby With Evidence Of Water Intrusion



# Restroom

Visible in photo is evidence of water intrusion

Ceiling in restroom has been removed



View from Lobby




Note: CCA funded electrical

Front Lobby Doors


Note evidence of water intrusion





## Concession Area, Interior and Exterior

Note: Damaged and missing tiles on floor and counters



View Towards Stage From Rear Of Auditorium





## View of South Side of the Auditorium

Note: Raked floor removed, walls obscured by drapes



View of Fly Loft and Ceiling in Auditorium,  
Both Funded with CCA grants



Rear of Building  
just outside the backstage  
entrance.







Backstage Area

Note, damage to wall (see enlarged image)



## Second Floor Sound Studio Area

Note: Windows Overlook Auditorium



## Second Floor Sound Studio Area



Note: damage to walls

## Second Floor Sound Studio Area



Note: cuts in wall, possibly to  
access interior sound equipment

