

Existing Conditions Photographs



East facade with existing ramp and entrance.



East facade, looking southwest.



East facade, looking north.



Front (south) facade, right sidewalk and stairs up to main entrance. Shows damaged concrete.



Front (south) facade, left sidewalk and stairs up to main entrance.



South facade main landing, showing concrete damage.



Looking south from main landing on south facade, western stairs and sidewalk.



Detail of western stairs and sidewalk off of main landing on south facade.



View west from western staircase off main landing on south facade.



Main landing at south facade entrance, showing concrete damage and previous repair.



Detailed view of eastern staircase and sidewalk on south facade.





View of south facade from west.



View of west facade, facing north.



View of existing railings on south facade, main entrance.