



Stewart Facility
5500 Snyder Avenue, Carson City, NV 89701

Request for Permission to Undertake Structural or Visual Alterations

In accord with the requirements set forth in existing covenants,
BUILDINGS & GROUNDS (name of agency) is requesting written permission
to undertake visual or structural alterations as described below:

Building Number and Name: #92 Boiler Room

Building's Date of Construction: 1921 EXPANDED IN 1939

Supplementary Information:

Please indicate if you have submitted the following—

- Written description of proposed work (*required; see second page*)
- Photographs of existing conditions (*required*)
- Sketches, plans, or architectural drawings depicting the proposed work
- Sketch or site plan of project location
- Specs of materials to be used
- Historic photographs depicting past condition or design
- Other

Request Submitted by:

Ron BODNAR [Signature]
 Print name Signature

Agency - BUILDING & GROUNDS
 Title - SUPERVISOR
 Email address - rbodner@admin.nv.gov
 Phone number - 690-8787

Date of Request: 4/3/17

Please allow up to 14 business days for this form to be processed. Proposed work must not begin until this form has been reviewed and approved by both the State Historic Preservation Office and the Nevada Indian Commission.

Please submit request form and supplementary materials to the State Historic Preservation Office, 901 S. Stewart St., Ste. 5004, Carson City, NV 89701-5248 or by email to rlpalmer@shpo.nv.gov.

REQUEST APPROVED BY:

SHPO - _____
Print and sign name *Date*

Nevada Indian Commission - _____
Print and sign name *Date*

Nevada Division of State Lands - _____
Print and sign name *Date*

Description of Proposed Work:

Please provide a thorough written description of the proposed work, including—

- Location on building
- Approximate size of area affected
- Existing conditions
- Materials to be used
- Proposed methods (must follow the [Secretary of the Interior's Standards](#))

(Use as many pages as needed)

Building #92 Boiler room Stewart Facility

At one time this was a bathroom facility with a wall around the toilet area, we would like to make it a bathroom again with a new toilet and utility sink and a wall that can be removed if need be. This looks to be the expanded area build in 1939, as you can see by the pictures the plumbing is still there so we can reuse it. Thanks.



