



Stewart Facility
5500 Snyder Avenue, Carson City, NV 89701

Request for Permission to Undertake Structural or Visual Alterations

In accord with the requirements set forth in existing covenants,
BUILDINGS & GROUNDS (name of agency) is requesting written permission
to undertake visual or structural alterations as described below:

Building Number and Name: #89 N.D.O.C

Building's Date of Construction: 1931

Supplementary Information:

Please indicate if you have submitted the following—

- Written description of proposed work (*required; see second page*)
- Photographs of existing conditions (*required*)
- Sketches, plans, or architectural drawings depicting the proposed work
- Sketch or site plan of project location
- Specs of materials to be used
- Historic photographs depicting past condition or design
- Other

Request Submitted by:

Ron BODNAR
Print name

[Signature]
Signature

Agency - BEG
Title - SUPERVISOR
Email address - rbodnar@admin.nv.gov
Phone number - 690-8787

Date of Request: 11/7/17

Please allow up to 14 business days for this form to be processed. Proposed work must not begin until this form has been reviewed and approved by both the State Historic Preservation Office and the Nevada Indian Commission.

Please submit request form and supplementary materials to the State Historic Preservation Office, 901 S. Stewart St., Ste. 5004, Carson City, NV 89701-5248 or by email to rlpalmer@shpo.nv.gov.

REQUEST APPROVED BY:

SHPO - _____
Print and sign name Date

Nevada Indian Commission - _____
Print and sign name Date

Description of Proposed Work:

Please provide a thorough written description of the proposed work, including—

- Location on building
- Approximate size of area affected
- Existing conditions
- Materials to be used
- Proposed methods (must follow the [Secretary of the Interior's Standards](#))


(Use as many pages as needed)

N.D.A.C. would like to remove the door connecting 2 supply rooms and put in sheetrock that will be taped, lightly sanded & painted. The H.V.A.C. system and building sprinkler system will NOT be affected.

NORTH

BLDG # 89

Supply Room








Serial Tag ID No. 5F7C6K2
 Qty 0027 of 0040 Tm # 1
 Dist PO # P332038728
 Order # 232038728
 System: Assembled in Mexico USA
 Model: H1
 Part # 232038728
 Mfg. # 5F7C6K2
 CTO
 M301 FS3-DC162
 40-628 CEVA-GRND
 OTM MISG

Serial Tag ID No. 5F86GK2
 Qty 0001 of 0020 Tm # 1
 Dist PO # P332038728
 Order # 232037290
 System: Assembled in Mexico USA
 Model: H1
 Part # 232037290
 Mfg. # 5F86GK2
 CTO
 M301 FS3-DC031
 40-628 FEDG-ELPA
 OTM MISG



Serial Tag ID No. 5F77GK2
 Qty 0001 of 0020 Tm # 1
 Dist PO # P332038728
 Order # 232037290
 System: Assembled in Mexico USA
 Model: H1
 Part # 232037290
 Mfg. # 5F77GK2
 CTO
 M301 FS3-DC031
 40-628 FEDG-ELPA
 OTM MISG