




































Project Name	Building Number	Date Received by SHPO	Estimated Due Date for SHPO comments	SHPO comments sent to NIC	State Lands Consultation (Y/N)	State Lands Comments Received	Project approved by NIC	Current Status or  or 
Mortar Repair	6	10/13/2016	11/13/2016	10/24/2016	N	n/a		
Building #4 Remodel	4	12/9/2016	12/23/2016	12/13/2016	Y; certification request recieved, 12/12/16	12/17/2016	12/14/2016	
Extend Window Opening	18	12/13/2016	12/27/2016	12/15/2016	N	n/a	12/15/2016	
Concrete Replacement	Between #3 and #4	12/22/2016	1/27/2017	1/23/2017	Y; certification request recieved, 1/13/17	1/23/2017	1/23/2017	
Concrete Slab, Ramp and Steps	84	4/28/2017	5/11/2017	5/5/2017	Y; certification request recieved, 4/28/17	5/5/2017	5/5/2017	
Boiler Room / Bathroom Rehab	92	5/3/2017	5/16/2017	5/5/2017	N	n/a	5/5/2017	
Parking Areas Concrete	Behind Building #3	5/10/2017	5/24/2017	5/19/2017	Y	5/19/2017	5/19/2017	
Bathroom Rehabilitation	44	6/29/2017	7/19/2017	6/30/2017	N	n/a	6/30/2017	
Repaint, Repair Wood and Concrete	27, 28, 29, 30, and 31	8/2/2017	8/21/2017	8/7/2017	N	n/a	8/8/2017	
Removal of White Board and Installation of Smart TV	107	8/2/2017	8/21/2017	8/7/2017	N	n/a	8/8/2017	
Tub Insert Replacement	13	8/31/2017	9/21/2017	9/5/2017	N	n/a	9/13/2017	
Clothes Line Removal Proposal	3	9/26/2017	10/13/2017	10/3/2017	Y	10/13/2017	10/6/2017	
Building #2 Proposal	2	8/10/2017		4/5/2018	N	n/a	4/5/2018	
Gym Repainting	160	10/18/2017	11/6/2017	10/20/2017	N	n/a	10/26/2017	
Gym Clean-up	20	11/2/2017	11/22/2017	11/15/2017	N	n/a	11/16/2017	
Door Installation	17	11/7/2017	11/29/2017	11/14/2017	N	n/a	11/15/2017	
Door Removal	89	11/7/2017	11/29/2017	11/14/2017	N	n/a	11/15/2017	
Electrical Installation	17	12/8/2017	12/29/2017	12/8/2017	N	n/a	12/12/2017	
Sink Replacement	3	12/27/2017	1/17/2018	1/2/2018	N	n/a	1/2/2018	
Sidewalk and Patio Repair/Replacement	11	1/5/2018	1/25/2018	1/16/2018	N	n/a	1/16/2018	
Floor Replacement and Painting, B & G Project	13	1/24/2018	2/12/2018	1/26/2018	N	n/a	1/26/2018	
Moisture Management	20	2/2/2018	2/22/2018	2/6/2018	Y	2/15/2018	2/20/2018	
Replace Doors to Classroom	107	2/2/2018	2/22/2018	2/6/2018	N	n/a	2/6/2018	
Floor Replacement and Kitchen Remodel	13	2/6/2018	2/26/2018	2/12/2018	N	n/a	2/20/2018	
Underground Electrical Replacement	107	3/30/2018	4/8/2018	4/10/2018	Y	4/10/2018	4/11/2018	
Gable Repair	48	4/11/2018	4/30/2018	4/16/2018	N	n/a	4/18/2018	
Drinking Fountain Repair	6	4/11/2018	4/30/2018	4/16/2018	N	n/a	4/18/2018	
Asbestos Abatement	1 and 2	5/1/2018	5/18/2018	5/2/2018	N	n/a	5/3/2018	
Window Sill Repair	107	5/3/2018	5/22/2018	5/10/2018	N	n/a	5/10/2018	
Wall Repair	107	5/3/2018	5/22/2018	5/10/2018	N	n/a	5/10/2018	
Sewer Repair	4	5/10/2018	5/30/2018	5/17/2018	Y	5/17/2018	5/18/2018	
Sewer Repair	32	5/10/2018	5/30/2018	5/17/2018	Y	5/17/2018	5/18/2018	
Asbestos Abatement	19	5/17/2018	6/6/2018	5/18/2018	N	n/a	5/18/2018	
Concrete work to improve ramp	19	6/15/2018	7/5/2018	6/19/2018	Y	6/19/2018	6/19/2018	