

# **Huntridge Theater**

**Las Vegas, Nevada**



Site Visits conducted by staff of the  
*Nevada State Historic Preservation Office*

*October 11, 2016*

*and*

*October 11, 2017*





File Photo 1 (early 1990s)




File Photo 2 (early 1990s)





Installation of the new roof (1997)





Installation of new security fencing; Restoration of marquee (late 1990s)

Photos from 2013-2017 visits

# Front Entrance & Marquee

CCA funded projects include (per file):

- Restoration of Marquee
- New glass at front entrance
- New tile at entrance





2013



2016



2016



2017






2013



2016



2016



2017





2013



2016



2016




2017






2013



2016



2016



2017






2013



2016



2016




2017







2013



2016



2016



2017



Photos from 2013-2017 visits

# Sidewalk, Paving & Fencing

CCA funded projects include (per file):

- Front block work
- Installation of concrete pad & exterior walkways
- Resurfacing of parking lot
- Installation of security fencing



2013



2016





2016



2017



2013





2016



2017



2013



2016



2016




2017








2013



2016




2016




2017





2013




2016





2016




2017




2013




2016



2016



2017





Photos from 2013-2017 visits

# Adjacent Building; Rear & side façades

CCA funded projects include (per file):

- Installation of security fencing
- Removal of old & installation of new air conditioning units
- Removal of old roof & installation of new roof
- Installation of fly loft



2013



2016





2016



2017

2013



2016





2016




2017





2013



2016





2016



2017



2013



2016





2016



2017



2013



2016





2016



2017



2013



2016





2016



2017

2013



2016





2016



2017



2013



2016





2016




2017



# Rear of Building – Just outside the backstage entrance



2016



2017



# Rear of Building – Just outside the backstage entrance



2016



2017

Photos from 2013-2017 visits

# General Maintenance

CCA funded projects include (per file):

- Updated electrical
- Installed/updated sprinkler & fire alarm system
- Rekeyed all locks





2013



2016



2016



2017






2013



2016




2016




2017






2013




2016





2016



2017






2013



2016



2016




2017





2013



2016



2016



2017





2013



2016



2016



2017



2013




2016



2016



2017





Photos from 2016 and 2017 visits

# Interior

CCA funded projects include (per file):

- Updated electrical
- Installation of sound system
- Installed/updated sprinkler & fire alarm system
  - Fly loft rigging
- Construction of snack bar
  - HVAC
- Flooring/Carpeting
- Completion of upstairs sound production rooms

# Lobby from Front Entrance



2016



2017



# Lobby Ceiling



2016



2017

## View toward Restroom from Lobby



2016



2017



# Restroom

Ceiling has been removed.  
Note CCA-funded electrical.



2016



2017

# Front Lobby Entrance

Note water damage



2016



2017



# Concession Area, Exterior

Note damaged and missing tiles



2016



2017

# Concession Area, Interior

Note damaged and missing tiles




2016



2017



# View towards Stage from Rear of Auditorium



# View towards Stage from Rear of Auditorium



2017




# View of South Side of Auditorium

Note: Raked floor removed;  
walls obscured by drapes



# View of South Side of Auditorium

Note: Raked floor removed;  
walls obscured by drapes





# View of Fly Loft and Ceiling in Auditorium

Both funded with CCA grants



2016

# View of Fly Loft and Ceiling in Auditorium

Both funded with CCA grants



2017



# Office Area

Note wall damage



2016




2017

# Stairs to Second Floor Sound Studio Area



2016



2017



# Second Floor Sound Studio Area

Windows overlook auditorium


2016




2017



## Second Floor Sound Studio Area



2016



2017



# Second Floor Sound Studio Area

Note: cuts in wall, possibly to  
access interior sound equipment



2016



2017

# Interior continued

Additional photos from 2017 visit



## Backstage Area (NE corner of building)



## Storage Area (Addition on SE corner of building)





## Auditorium – Looking west toward lobby



# Second Floor Sound Studio Area

